

**TECHNICAL SERVICE BULLETIN****NUMBER:** 09-012-22**GROUP:** 09 - Engine**DATE:** October 1, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Spark Knock/Engine Symptoms

OVERVIEW:

This bulletin involves cleaning the piston heads and cylinder head combustion chambers to resolve a spark knock condition being caused by oil intrusion through the PCV system.

MODELS:

2018 - 2022	(JL)	Jeep Wrangler
2020 - 2022	(JT)	Jeep Gladiator
2018 - 2022	(WK)	Jeep Grand Cherokee

NOTE: This bulletin applies to vehicles within the following markets/countries: North America, India/Asia Pacific, Middle East/Africa, and Enlarged Europe.

NOTE: This bulletin applies to:

- JL vehicles built equipped with a 3.6L V6 24V VVT Engine (Sales Code ERC) or a 3.6L V6 24V VVT E-torque Engine (Sales Code ERG).
- JT vehicles built equipped with a 3.6L V6 24V VVT Engine (Sales Code ERC).